

**PLUGGING RECORD**

OAC 165:10-1-10

**WELL INFORMATION**

**Plug Date: November 24, 2014**

**API No:** 3504521693

**Well #:** 2

**Well Name:** BRANDENBURG UNIT

**Operator:** MEWBOURNE OIL COMPANY

**Operator #:** 6722

**Section:** 27      **Township:** 22N      **Range:** 26W      **Meridian:** Indian

**SW4 1/4:**      **NE4 1/4:**      **SW4 1/4:**      **NW4 1/4:**

**Total Depth:** 0      **Base of Treatable:** Water: 0      **Well Classification:** GAS

**CONTACT INFORMATION**

**Contact Name:** Sue Hearon

**Telephone:** 4053500814

**Address 1:** 3620 OLD BULLARD RD

**Address 2:** PO BOX 7698

**City:** TYLER      **State:** TX      **Zipcode:** 75711-7698      **Country:** US

**Email Address:**

**Fax:**

**PIPE RECORDS**

**PERFORATION DEPTHS**

String Name	Size	Run	Pulled
CONDUCTOR	20	77	0
SURFACE	8.625	2084	0
PRODUCTION	4.5	9580	2166

From Depth	To Depth
9230	39

**PLUGS**

Plug Type	Hole Size	Depth	No. Sacks of Cement	Slurry Volume	Calculated TOC	Top of Plug
CEM	4.5	4540	35	41	0	0
CIBP + CEM	4.5	4550	1	1	4540	4540
CEM	8.625	2135	75	88	1935	1935
CEM	8.625	650	35	41	550	550
CEM	8.625	34	10	12	4	4

**Remarks:**

**Reason For Plugging:** UNECONOMICAL

**CEMENTER CERTIFICATION INFORMATION**

**Name:**      **Title:**

**Company Name:** SARGENT & LILLARD CASING PULL

**Permit No:** 803

**Address 1:** 1506 CEDAR

**Address 2:** P.O. Box 1450

**City:** WOODWARD      **State:** OK      **Zipcode:** 73802-1450      **Phone:** (580) 254-1881

I declare that I have knowledge of the contents of this report and am authorized by my organization to make this report, which was prepared by me or under my supervision and direction with the data and facts stated herein to be true, correct and complete to the best of my knowledge and belief.

Electronic Signature: MEWBOURNE OIL COMPANY