

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35019262790000

Completion Report

Spud Date: September 01, 2017

OTC Prod. Unit No.: 019-222463

Drilling Finished Date: October 28, 2017

1st Prod Date: December 22, 2017

Completion Date: December 17, 2017

Drill Type: HORIZONTAL HOLE

Well Name: DOC BROWN 3-30-19XH

Purchaser/Measurer:

Location: CARTER 30 3S 2W
NW NE SE SE
1090 FSL 535 FEL of 1/4 SEC
Derrick Elevation: 0 Ground Elevation: 0

First Sales Date:

Operator: AVALON OPERATING LLC 23929

15 W 6TH ST STE 2300
TULSA, OK 74119-5401

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
675196	

Increased Density	
Order No	
665646	
668316 NPT	
665645	
668315 NPT	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	20			100		10	SURFACE
SURFACE	13 3/8	54.5	J-55	1168	1500	710	SURFACE
INTERMEDIATE	9 5/8	40	P-110	8324	1500	370	6350
PRODUCTION	5 1/2	20	P-110	17160	7000	2440	4535

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 17130

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Dec 25, 2017	WOODFORD	68	36.3	520	7647	406	JET LIFT	1000	64	125

Completion and Test Data by Producing Formation

Formation Name: WOODFORD		Code: 319WDFD		Class: OIL	
Spacing Orders			Perforated Intervals		
Order No	Unit Size	From	To		
643868	640	9919	17120		
647308	640				
675005	MULTIUNIT				
Acid Volumes			Fracture Treatments		
NONE			220M BARRELS SLICK WATER, 7.7MM POUNDS SAND		

Formation	Top
WOODFORD	8754

Were open hole logs run? No
Date last log run:

Were unusual drilling circumstances encountered? No
Explanation:

Other Remarks
There are no Other Remarks.

Lateral Holes
Sec: 19 TWP: 3S RGE: 2W County: CARTER
NW SE SW NW
2305 FNL 681 FWL of 1/4 SEC
Depth of Deviation: 7558 Radius of Turn: 401 Direction: 336 Total Length: 8942
Measured Total Depth: 17130 True Vertical Depth: 7959 End Pt. Location From Release, Unit or Property Line: 681

FOR COMMISSION USE ONLY	
Status: Accepted	1140638