

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35087213130001

Completion Report

Spud Date: April 04, 1986

OTC Prod. Unit No.: 087-089740-0-0000

Drilling Finished Date: May 27, 1986

Amended

1st Prod Date: July 17, 1986

Amend Reason: ADD FRAC TREATMENT

Completion Date: July 17, 1986

Recomplete Date: November 18, 2019

Drill Type: SERVICE WELL

Well Name: BROWN 1-3

Purchaser/Measurer:

Location: MCCLAIN 3 5N 4W
NE SE NE SE
1800 FSL 2475 FWL of 1/4 SEC
Latitude: 34.933156 Longitude: -97.60232
Derrick Elevation: 1130 Ground Elevation: 1120

First Sales Date:

Operator: ROX EXPLORATION INC 18783

2416 PALMER CIR
NORMAN, OK 73069-6301

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
295264	

Increased Density	
Order No	
There are no Increased Density records to display.	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	16		J-55	43		4	SURFACE
SURFACE	9.625	36	K55	1015	2000	450	SURFACE
PRODUCTION	5.5	17	N80	12330	1000	400	10250

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4.5	13.5	P110	10764	1000	152	0	10764

Total Depth: 12330

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
12142	CIBP

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Nov 27, 2019	1ST BROMIDE	24	40	15	6250	43	PUMPING		64/64	

Completion and Test Data by Producing Formation

Formation Name: 1ST BROMIDE

Code: 202BRMD1

Class: OIL

Spacing Orders

Order No	Unit Size
252026	80

Perforated Intervals

From	To
11969	12107

Acid Volumes

There are no Acid Volume records to display.

Fracture Treatments

4,322 BBLS FLUID
154,700 LBS PROPPANT

Formation	Top
1ST BROMIDE	12018

Were open hole logs run? Yes

Date last log run: May 27, 1986

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

FOR COMMISSION USE ONLY

1144493

Status: Accepted