

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35087222590000

Completion Report

Spud Date: August 21, 2019

OTC Prod. Unit No.: 087-226166-0-0000

Drilling Finished Date: September 07, 2019

1st Prod Date: December 09, 2019

Completion Date: September 30, 2019

Drill Type: HORIZONTAL HOLE

Well Name: KILKENNY 2-6MH

Purchaser/Measurer: SOUTHWEST

Location: MCCLAIN 6 5N 4W
NE NW NE NE
275 FNL 680 FEL of 1/4 SEC
Latitude: 34.94166467 Longitude: -97.65509815
Derrick Elevation: 1195 Ground Elevation: 1180

First Sales Date: 12/11/2019

Operator: CASILLAS OPERATING LLC 23838

401 S BOSTON AVE STE 2400
TULSA, OK 74103-4060

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	709843		710228	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	40.00	J-55	1475		375	SURFACE
PRODUCTION	5.5	20.00	P-110	16749		1180	4928

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 16777

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Dec 14, 2019	MISSISSIPPIAN	648	46	1067	1647	940	FLOWING	1506	92/128	1861

Completion and Test Data by Producing Formation

Formation Name: MISSISSIPPIAN

Code: 359MSSP

Class: OIL

Spacing Orders

Order No	Unit Size
698903	640

Perforated Intervals

From	To
11911	16672

Acid Volumes

408 BBLS HCL ACID

Fracture Treatments

302,770 BBLS FLUID 9,981,047 LBS PROPPANT
--

Formation	Top
SYCAMORE	11685

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 6 TWP: 5N RGE: 4W County: MCCLAIN

SE SE SW SE

281 FSL 1483 FEL of 1/4 SEC

Depth of Deviation: 11321 Radius of Turn: 442 Direction: 182 Total Length: 4761

Measured Total Depth: 16777 True Vertical Depth: 11348 End Pt. Location From Release, Unit or Property Line: 281

FOR COMMISSION USE ONLY

1144692

Status: Accepted