

Oklahoma Corporation Commission
 Oil & Gas Conservation Division
 Post Office Box 52000
 Oklahoma City, Oklahoma 73152-2000
 Rule 165: 10-3-25

Form 1002A

API No.: 35051248230000

Completion Report

Spud Date: August 12, 2021

OTC Prod. Unit No.: 051-228013-0-0000

Drilling Finished Date: December 03, 2021

1st Prod Date: May 26, 2022

Completion Date: May 26, 2022

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: TODD 5H-26-35

Purchaser/Measurer: BLUE MOUNTAIN
 MIDSTREAM

Location: GRADY 26 10N 5W
 SW SE SW NW
 2362 FNL 887 FWL of 1/4 SEC
 Latitude: 35.31344372 Longitude: -97.70294635
 Derrick Elevation: 1234 Ground Elevation: 1209

First Sales Date: 5/26/2022

Operator: CITIZEN ENERGY III LLC 24120

320 S BOSTON AVE STE 900
 TULSA, OK 74103-3729

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
726623	

Increased Density	
Order No	
726490	
726491	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	40	J-55	1010		270	SURFACE
PRODUCTION	7	29	P-110	8475		311	4500

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4.5	13.5	P-110	8714	0	624	8296	17010

Total Depth: 17010

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Jun 10, 2022	WOODFORD	614	41.1	1488	2423	1196	FLOWING	1200	30	951

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders

Order No	Unit Size
661126	640
656205	640
726622	MULT UNIT

Perforated Intervals

From	To
9194	16957

Acid Volumes

20,008 GALLONS OF 15% HCl

Fracture Treatments

15,610,000 POUNDS OF PROPPANT ; 357,576 BARRELS OF FRAC FLUID

Formation	Top
WOODFORD	8934

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 35 TWP: 10N RGE: 5W County: GRADY

SE SE SW SW

126 FSL 1315 FWL of 1/4 SEC

Depth of Deviation: 8534 Radius of Turn: 458 Direction: 179 Total Length: 8077

Measured Total Depth: 17010 True Vertical Depth: 9124 End Pt. Location From Release, Unit or Property Line: 126

FOR COMMISSION USE ONLY

1148600

Status: Accepted