

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35049253470000

Completion Report

Spud Date: October 02, 2021

OTC Prod. Unit No.: 049-227800-0-0000

Drilling Finished Date: January 01, 2021

1st Prod Date: March 25, 2022

Completion Date: March 24, 2022

Drill Type: HORIZONTAL HOLE

Well Name: RCL 7-19-30-31XHW

Purchaser/Measurer: ENABLE MIDSTREAM PARTNERS

Location: GARVIN 19 3N 4W
NE NW NE NE
320 FNL 970 FEL of 1/4 SEC
Latitude: 34.723982 Longitude: -97.653804
Derrick Elevation: 1250 Ground Elevation: 1225

First Sales Date: 03/25/2022

Operator: CONTINENTAL RESOURCES INC 3186

PO BOX 268870
OKLAHOMA CITY, OK 73126-8870

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
	725870

Increased Density	
Order No	
	721869
	721871
	721870

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	20	94	K-55	80			0
SURFACE	13 3/8	55	J-55	1500		683	1200
INTERMEDIATE	9 5/8	40	P-110	12727		1394	3000
PRODUCTION	5 1/2	23	P-110	29970		3276	8727

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 29770

Packer	
Depth	Brand & Type
N/A	N/A

Plug	
Depth	Plug Type
N/A	N/A

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Mar 31, 2022	WOODFORD	87	51	2978	34230	4344	FLOWING	1069	40	

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: GAS

Spacing Orders

Order No	Unit Size
190289	640
608544	640
213539	640
725548	MULTIUNIT

Perforated Intervals

From	To
14843	19426
19463	24700
24729	29677

Acid Volumes

1245 BBLs 15% HCL

Fracture Treatments

818,706 BBLs FLUID & 31,756,862 LBS OF SAND

Formation	Top
WOODFORD	14692

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 31 TWP: 3N RGE: 4W County: GARVIN

SW SE SE SE

274 FSL 484 FEL of 1/4 SEC

Depth of Deviation: 14300 Radius of Turn: 673 Direction: 180 Total Length: 14927

Measured Total Depth: 29770 True Vertical Depth: 15355 End Pt. Location From Release, Unit or Property Line: 274

FOR COMMISSION USE ONLY

1147916

Status: Accepted