

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35087223270000

Completion Report

Spud Date: November 13, 2021

OTC Prod. Unit No.: 087-227704

Drilling Finished Date: December 26, 2021

1st Prod Date: March 09, 2022

Completion Date: March 04, 2022

Drill Type: HORIZONTAL HOLE

Well Name: CHARLES 0804 34-3 3WXH

Purchaser/Measurer: ENABLE

Location: MCCLAIN 34 8N 4W
SE SE NE NW
1053 FNL 2478 FWL of 1/4 SEC
Latitude: 35.128543 Longitude: -97.60942
Derrick Elevation: 1216 Ground Elevation: 1192

First Sales Date: 3/9/2022

Operator: NATIVE EXPLORATION OPERATING LLC 24070

123 NW 8TH ST
OKLAHOMA CITY, OK 73102-5804

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
724777	

Increased Density	
Order No	
720716	
720562	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	40#	J-55	1467		380	SURFACE
PRODUCTION	5.5	20#	P-110	20416		2435	1075

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 20421

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Mar 31, 2022	WOODFORD	1023	44	942	921	1742	GAS LIFT		128/128	1674

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders

Order No	Unit Size
681783	640
681782	640
724776	MULTIUNIT

Perforated Intervals

From	To
10101	15209
15209	20320

Acid Volumes

There are no Acid Volume records to display.

Fracture Treatments

714,973 BBLS WATER
25,376,980 LBS PROPPANT

Formation	Top
WOODFORD	9573

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 3 TWP: 7N RGE: 4W County: MCCLAIN

SE SW SW SE

83 FSL 2137 FEL of 1/4 SEC

Depth of Deviation: 9520 Radius of Turn: 581 Direction: 180 Total Length: 10320

Measured Total Depth: 20421 True Vertical Depth: 9976 End Pt. Location From Release, Unit or Property Line: 83

FOR COMMISSION USE ONLY

1148208

Status: Accepted