

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35087223240000

Completion Report

Spud Date: October 08, 2021

OTC Prod. Unit No.: 087-227775-0-0000

Drilling Finished Date: December 19, 2021

1st Prod Date: March 14, 2022

Completion Date: March 14, 2022

Drill Type: HORIZONTAL HOLE

Well Name: WENDLING 0704 3H-30XX

Purchaser/Measurer: ENABLE

Location: MCCLAIN 30 7N 4W
NW SE NE NW
725 FNL 2216 FWL of 1/4 SEC
Latitude: 35.056638 Longitude: -97.662794
Derrick Elevation: 1343 Ground Elevation: 1313

First Sales Date: 3/14/2022

Operator: OVINTIV USA INC 21713

4 WATERWAY SQUARE PLACE, STE 100
THE WOODLANDS, TX 77380-3197

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
727271	

Increased Density	
Order No	
727470	
721151	
721758	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	13 3/8	54.5	J-55	1467		710	SURFACE
INTERMEDIATE	8 5/8	32	HCL 80	10695		1480	783
PRODUCTION	5 1/2	20	P-110	27016		2320	5903

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 27046

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Apr 13, 2022	WOODFORD	879	46	898	1022	1166	FLOWING	2000	124	1573

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders

Order No	Unit Size
658908	640
633223	640
727410	MULTI UNIT

Perforated Intervals

From	To
11432	16552
16552	21848
21848	26991

Acid Volumes

TOTAL HCL 15% - 9555GAL

Fracture Treatments

TOTAL FLUID - 751,089BBLS TOTAL PROPPANT - 30,990,788LBS

Formation	Top
WOODFORD	10917

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 6 TWP: 6N RGE: 4W County: MCCLAIN

SE SW SE SW

109 FSL 1880 FWL of 1/4 SEC

Depth of Deviation: 10415 Radius of Turn: 477 Direction: 180 Total Length: 15559

Measured Total Depth: 27046 True Vertical Depth: 11418 End Pt. Location From Release, Unit or Property Line: 109

FOR COMMISSION USE ONLY

1148119

Status: Accepted