

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35051249420000

Completion Report

Spud Date: June 03, 2022

OTC Prod. Unit No.: 051-230551

Drilling Finished Date: July 16, 2022

1st Prod Date: October 26, 2022

Completion Date: October 26, 2022

Drill Type: HORIZONTAL HOLE

Well Name: JOHNSON 1H-6

Purchaser/Measurer: BLUE MOUNTAIN
MIDSTREAM

Location: GRADY 6 7N 5W
S2 SW SE SW
205 FSL 1650 FWL of 1/4 SEC
Latitude: 35.102693 Longitude: -97.77037179
Derrick Elevation: 1296 Ground Elevation: 1266

First Sales Date: 10/26/2022

Operator: CITIZEN ENERGY III LLC 24120

320 S BOSTON AVE STE 900
TULSA, OK 74103-3729

Completion Type		Location Exception	Increased Density
X	Single Zone	Order No	Order No
	Multiple Zone	There are no Location Exception records to display.	726038
	Commingled		

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9.625	40	J-55	1007	1000	292	SURFACE
PRODUCTION	7	29	P-110 EC	11500	1500	455	8000

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4.5	13.5	P-110 HC	5967	1000	415	11309	17276

Total Depth: 17276

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Nov 22, 2022	WOODFORD	483	44.3	470	973	1631	GAS LIFT	2100	128	142

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders

Order No	Unit Size
663980	640

Perforated Intervals

From	To
12277	17227

Acid Volumes

There are no Acid Volume records to display.

Fracture Treatments

12,514,982 POUNDS OF PROPPANT ; 281,298 BARRELS OF FLUID

Formation	Top
WOODFORD	11940

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 6 TWP: 7N RGE: 5W County: GRADY

NW NE NW NW

126 FNL 678 FWL of 1/4 SEC

Depth of Deviation: 11722 Radius of Turn: 314 Direction: 359 Total Length: 4942

Measured Total Depth: 17276 True Vertical Depth: 11711 End Pt. Location From Release, Unit or Property Line: 126

FOR COMMISSION USE ONLY

1149395

Status: Accepted