

Oklahoma Corporation Commission  
Oil & Gas Conservation Division  
Post Office Box 52000  
Oklahoma City, Oklahoma 73152-2000  
Rule 165: 10-3-25

Form 1002A

API No.: 35093252720000

**Completion Report**

Spud Date: March 31, 2022

OTC Prod. Unit No.: 09322813800000

Drilling Finished Date: July 05, 2022

1st Prod Date: August 07, 2022

Completion Date: August 07, 2022

**Drill Type: HORIZONTAL HOLE**

Well Name: BISON 2312 1UOH-34

Purchaser/Measurer: TALL OAK

Location: MAJOR 27 23N 12W  
SE SW SW SW  
260 FSL 621 FWL of 1/4 SEC  
Latitude: 36.434864 Longitude: -98.477562  
Derrick Elevation: 1308 Ground Elevation: 1285

First Sales Date: 8/8/22

Operator: CANVAS ENERGY LLC 16896

4700 GAILLARDIA PARKWAY STE 200  
OKLAHOMA CITY, OK 73142-1839

Completion Type		Location Exception		Increased Density	
X	Single Zone	<b>Order No</b>		<b>Order No</b>	
	Multiple Zone	732462		725522	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	9 5/8	36	J-55	1469		445	SURFACE
PRODUCTION	7	26	P-110	7008		250	2867

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4 1/2	11.6	P-110	5768	0	365	6431	12199

**Total Depth: 12209**

Packer	
Depth	Brand & Type
6371	AS-III

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Sep 13, 2022	MISSISSIPPI LIME	365	38.3	144	395	1523	GAS LIFT	670	64/64	124

**Completion and Test Data by Producing Formation**

Formation Name: MISSISSIPPI LIME

Code: 351MSSLM

Class: OIL

**Spacing Orders**

Order No	Unit Size
63692	640
725333	640

**Perforated Intervals**

From	To
7185	12095

**Acid Volumes**

There are no Acid Volume records to display.

**Fracture Treatments**

263,116 BBLS TREATED FRAC WATER
10,964,998# PROPPANT

Formation	Top
MISSISSIPPI LIME	7185

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

**Other Remarks**

There are no Other Remarks.

**Lateral Holes**

Sec: 34 TWP: 23N RGE: 12W County: MAJOR

SW SE SW SW

56 FSL 896 FWL of 1/4 SEC

Depth of Deviation: 6447 Radius of Turn: 486 Direction: 178 Total Length: 4910

Measured Total Depth: 12209 True Vertical Depth: 6972 End Pt. Location From Release, Unit or Property Line: 56

**FOR COMMISSION USE ONLY**

1148918

Status: Accepted